TUBE SURFACE MOUNTED PROFILE

DARKON


Ensure that products are mounted with supplied, recommended or appropriate screws and fixings to suit the mounting surface.

WARNING

INSTALLATION IS ONLY TO BE CARRIED OUT BY SUITABLY QUALIFIED PERSONS IN ACCORDANCE WITH INSTALLATION INSTRUCTIONS AND ALL APPLICABLE REGULATIONS OR STANDARDS. (IMPROPER INSTALLATION CAN CREATE AN ELECTRICAL HAZARD WITH RISK OF ELECTRIC SHOCK, FIRE OR INJURY). DARKON WILL NOT BE HELD RESPONSIBLE FOR ANY CONSEQUENCES ARISING FROM IMPROPER PRODUCT HANDLING, STORAGE OR INSTALLATION.

TOOLS REQUIRED

POWER DRILL / DRILL BIT / PHILLIPS DRIVER / PENCIL / PLIERS / TAPE MEASURE / PLUM LASER



COMPONENTS








С







Ø69


MAINTENANCE



Wipe product with a clean dry microfiber cloth. Do not use any cleaning products/ chemicals to clean product.


SERVICING


THIS IN A NON-SERVICEABLE FITTING. REMOTE POWER SUPPLY CAN BE REPLACED IF DEEMED FAULTY.






04.10.23









I. Unassemble Tube lens assembly(A) from Surfacebody(B)



3.


Project line using laser plumb and mark necessary mounting points See Figure 1 for reference.






2400

Pull powercable (240V) through cutout.



6.

Fix the **Surfacebody(B)** onto the ceiling with appropriate fasteners (*not supplied*).




5.

8.


7.

Fasten earth lug to threaded detail on endcap.




Wire primary wires into terminal.

1



9. Wire primary wires into terminal Wire dimming wires into terminal.

04.10.23



8.

Install **Tube lens assembly(A)** to **Surfacebody(B)** Apply gentle pressure to the sides of the tube lens to help it seat inside the Surfacebody.

9.

Ensure proper installation by clipping Mainbody to Surfacebody snap-fit detail. Centre **Tube lens assembly(A)**.

3/3